

EntraGuard® Platinum: Firmware v9.0.3

1.0 EntraGuard Platinum Firmware v9.0.3

This firmware release makes the following improvements:

1. Specific model names have been removed from the menu listing. All EntraGuard units will simply display EntraGuard.
2. Due to the change in US Federal law governing the beginning and ending dates for Daylight Saving Time, the firmware has been changed to reflect the new dates. Beginning in 2007 Daylight Saving Time will “Spring Forward” on the second Sunday in March. Daylight Saving Time will “Fall Back” on the first Sunday in November. To bypass the firmware update, refer to the Daylight Saving Adjustment Application Note (P/N 01980-001).

2.0 Compatibility

- Firmware release v9.0.3, PIC16 v1.0.10, and PIC18 v3.0.1 can only be used in EntraGuard Platinum controllers. The leading '8' digit in the release number indicates that this release is for the EntraGuard Platinum.
- Firmware PROM v9.0.3, PIC 16 v1.0.10, and PIC 18 v3.0.1 are interconnected and all must be installed on an EntraGuard Platinum controller for proper operation.
- Firmware release v9.0.3 and *Doors* v4.50 (or higher) must be used together to enable all the new features offered by this firmware release.
- To ensure proper EntraGuard Platinum operation with *Doors* software, *Doors* must be at v4.43 or higher.
- To ensure proper PXL-500/PXL-510 operation with *Doors* software in mixed EntraGuard Platinum/PXL access control networks, *Doors* v4.43 (or higher) **only** supports PXL-500/PXL-510 controllers with v8.4.43 or higher firmware.
- When an EntraGuard Platinum is to be used as a slave to a PXL-500/PXL-510 master controller, the PXL-500/PXL-510 must have firmware v8.4.43 or higher.
- EntraGuard Platinum is not compatible with PXL-250 and PXL-100 controllers.

NOTE: For specific compatibility information, refer to the Series 3 and 4 Compatibility Guide (P/N 01876-001).

3.0 Known Issues

There are no known issues.

End of document.

