

NXT Controller Firmware v2.2.14

Release Notes

1.0 Firmware Release

Release of the *NXT* Controller firmware v2.2.14.

2.0 Known Issues

The *NXT* Controller firmware v2.2.14 has the following known issues:

1. Removing power from an *NXT* controller quickly after performing a system reset may cause the controller's flash memory to lose ALL of its network configuration data. To prevent this from happening, please follow the instructions given in the *NXT 2-D/4-D Controller Installation Guide* (P/N: 0197-001).
2. If a reader is annunciating a Door Forced or Door Held Open alarm and the Door Switch input property is changed to "Unassigned," the reader's beeper will continue to beep after the update has been completed. Verify that any local alarms have been cleared before changing the Door Switch input property.

3.0 Compatibility

NXT Controllers with firmware v2.2.14 is ONLY compatible with the following:

DoorsNXT - Software v2.1.0

NXT-4x4 - Firmware v02.02.03 or greater

NXT-RIM (Reader Interface Modules) - Firmware v2.02.10 or greater

NXT Readers - Firmware v2.00.01 or greater

NXT Controllers are compatible with MS readers, 26-Bit Wiegand readers, and non-26-Bit Wiegand readers in connection with the use of an *NXT-RIM*.

Contact Keri Systems:

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: + 44 (0) 870 444 7234
Fax: (408) 435-7163	Fax: + 44 (0) 1763 274 106
Web: www.kerisys.com	Web: www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk

End of document.