

PXL-250: Firmware v6.3.59

1.0 PXL-250 Firmware v6.3.59

The PXL-250 Firmware v6.3.59 makes two firmware fixes.

1. When a door is within an Auto Lock schedule and is manually unlocked in Doors by the operator, the door will remain unlocked even after a local RTE relock following the door being opened and closed.
2. A door that has been placed in a Global Unlock state and is followed by a subsequent RTE relock after the expiration of the Door Lock Time will remain unlocked.

2.0 Application

Firmware release 6.3.59 (EPROM v6.3.59 and MIOP v1.10) can only be used in PXL-250 controllers. The leading '6' digit in the release number indicates that this release is for the PXL-250.

3.0 Compatibility

- EPROM 6.3.59 and MIOP v1.09 or v1.10 are interconnected and both must be installed on a controller for proper operation.
- Firmware release 6.3.59 and *Doors* v3.63 (or higher) must be used together to enable all the new features offered by this firmware release.
- *Doors* only supports PXL-250 controllers with v6.3.20 or greater firmware. PXL-100 controllers are not compatible with *Doors*.

NOTE: For additional compatibility information, see the Compatibility Guide - Series 3 (P/N 01876-001).



PXL-250: Firmware v6.3.59

Release Notes

PXL-250

This page is intentionally left blank.



1530 Old Oakland Road, Suite 100
San Jose, CA 95112 USA
(800) 260-5265 (408) 451-2520 FAX (408) 441-0309
Web: <http://www.kerisys.com> E-mail: sales@kerisys.com

01853-104 Rev. A

Page 2 of 2