

NXT RIM Firmware v03.01.11

Release Notes

Section 1 - Reader Interface Module (RIM) Firmware Release

Section 2 - Known Issues

Section 3 - Compatibility

Section 4 - Contact Keri Systems

1.0 Reader Interface Module (RIM) Firmware Release

NXT RIM firmware v03.01.11 contains the following correction:

1. Under certain conditions, typically when “hot-swapping” readers or in unusually EMI noisy environments, the RIM’s Data0 and Data1 lines could be pulled into a both-lines-low state. This is illegal per the Wiegand specification, and because of this it was not properly managed by the firmware. Changes were made in the firmware to recognize this state and prevent this condition from being processed.

2.0 Known Issues

In MS mode, noise on the communication line has been seen that can create a “ghost read” that appears in the event log as an Unknown Card in NetXtreme applications or as Not In File for Doors.Net applications.

3.0 Compatibility

NXT RIM units with firmware v03.01.11 is ONLY compatible with the following:

Doors.Net

Controller firmware version 2.4.17 or greater. Software version v3.5.1.8 or greater.

NetXtreme

Controller firmware version 02.03.12 or greater. Software version v2.4.0.

NXT RIMs are compatible with MS readers, 26-Bit Wiegand readers, non-26-Bit Wiegand readers (64-bit maximum), and HID readers.

4.0 Contact Keri Systems

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: 44 (0) 1763 273 243
Fax: (408) 435-7163	Fax:+ 44 (0) 1763 274 106
Web: www.kerisys.com	Web:www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail:sales@kerisystems.co.uk tech-support@kerisystems.co.uk

End of document.