

EntraGuard® Platinum: Firmware v9.0.1

1.0 EntraGuard Platinum Firmware v9.0.1

The EntraGuard Platinum Firmware v9.0.1 is the initial release of the EntraGuard Platinum controller firmware.

2.0 Compatibility

- Firmware release v9.0.1, PIC16 v1.0.10, and PIC18 v3.0.1 can only be used in EntraGuard Platinum controllers. The leading '8' digit in the release number indicates that this release is for the EntraGuard Platinum.
- Firmware PROM v9.0.1, PIC 16 v1.0.10, and PIC 18 v3.0.1 are interconnected and all must be installed on an EntraGuard Platinum controller for proper operation.
- Firmware release v9.0.1 and *Doors* v4.43 (or higher) must be used together to enable all the new features offered by this firmware release.
- To ensure proper EntraGuard Platinum operation with *Doors* software, *Doors* must be at v4.43 or higher.
- To ensure proper PXL-500/PXL-510 operation with *Doors* software in mixed EntraGuard Platinum/PXL access control networks, *Doors* v4.43 (or higher) **only** supports PXL-500/PXL-510 controllers with v8.4.43 or higher firmware.
- When an EntraGuard Platinum is to be used as a slave to a PXL-500/PXL-510 master controller, the PXL-500/PXL-510 must have firmware v8.4.43 or higher.
- EntraGuard Platinum is not compatible with PXL-250 and PXL-100 controllers.

NOTE: For additional compatibility information, see the Compatibility Guide - Series 3 (P/N 01876-001).

3.0 Known Issues

There are no known issues.

End of document.

