

NXT Controller Firmware v2.05.22

Release Notes

1.0 NXT Controller Firmware Release

NXT Controller firmware v02.05.22 makes the following improvements:

1. Corrects an issue where presenting the same credential to a Reader multiple times would cause the Controller to process the same credential data multiple times, delaying the controller from processing data from a new credential. This additional processing time, in turn, would delay the unlocking of the door for the new credential.
2. Corrects an issue with incremental credential adds and deletes that prevented some credentials from being granted access until a full card holder database update was performed.

2.0 Known Issues

None at this time.

3.0 Compatibility

NXT Controllers with firmware v02.05.22 is ONLY compatible with the following:

Doors.NET - Software v3.5.1.14 or greater

NXT-4x4 - Firmware v3.00.02 or greater

NXT-RIM (Reader Interface Modules) - Firmware v3.02.05 or greater

NXT Reader - Firmware v3.00.01 or v3.01.01 or greater

NXT Controllers are compatible with MS readers, 26-Bit Wiegand readers, and non-26-Bit Wiegand readers only when connected via an NXT-RIM.

4.0 Contact Keri Systems

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: + 44 (0) 1763 273 243
Fax: (408) 577-1792	Fax: + 44 (0) 1763 274 106
Web: www.kerisys.com	Web: www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk

End of document.