

PXL-500/PXL-510: Firmware v8.4.46

1.0 PXL-500/PXL-510 Firmware v8.4.46

PXL-500/PXL-510 Firmware v8.4.46 contains two fixes:

1. When a fax machine called a PXL, the connection process would fail, putting the PXL into “direct connect” mode. If *Doors* uses a modem to connect with the PXL, it would no longer be able to do so. This has been fixed so that the connection mode is not changed when a fax machine calls a PXL.
2. On PXL proximity panels only, the doors A lock relay would unlock whenever power is first applied to the panel. This has been changed so that no longer occurs. This change does not affect Wiegand PXL panels.

2.0 Compatibility

- Firmware release 8.4.46 (PROM v8.4.45 and PIC v2.11) can only be used in PXL-500/PXL-510 controllers. The leading '8' digit in the release number indicates that this release is for the PXL-500/PXL-510.
- PROM 8.4.46 and PIC v2.11 are interconnected and both must be installed on a controller for proper operation.
- Firmware release 8.4.46 and *Doors* version 4.50 must be used together to enable all the new features offered by this firmware release.
- An SB-593 is compatible with both a PXL-500/PXL-510 and a PXL-250 (the extra row of connector pins on the SB-593 will “hang” over the PXL-250’s mounting holes).
- A PXL-500/PXL-510 can be added to any existing PXL-250 network and it will function just like a PXL-250. The PXL-500/PXL-510 has additional functionality in terms of card capacity and other features. If PXL-500s/PXL-510s are added to an existing PXL-250 network and the new features will be used (such as Temp Cards), then a PXL-500/PXL-510 must be installed as the master and any controller location that will use the function must also have a PXL-500/PXL-510 in place.
- If Alarm Control integration with a NetworX NX-8E alarm panel will be used, a PXL-510 **MUST** be used as the master. This is true for either a PXL-250 network, a PXL-500 network, or a mixed PXL-250/PXL-500 network. In a PXL-250 or a mixed network, any doors participating in alarm control must use a PXL-500/PXL-510.
- When implementing a PXL-500 system that will also incorporate EntraGuard telephone entry, the telephone entry unit is no longer required to be the master. PXL-250/EntraGuard mixed systems still require an EntraGuard as the master controller.

NOTE: For specific compatibility information, refer to the Series 3 and 4 Compatibility Guide (P/N 01876-001).

3.0 Known Issues

There are no known issues.

PXL-500/PXL-510: Firmware v8.4.46

Release Notes

PXL-500 / PXL-510

End of the document.