

NXT Readers Firmware v2.00.03

Release Notes

1.0 Firmware Release

NXT Readers firmware release v2.00.03 makes the following correction.

1. When a Status Request Command was issued from the controller, the reader would not report it's revision number. The revision number would only be reported when the reader was powered up. This has been fixed.

2.0 Known Issues

The NXT Readers firmware v2.00.02 has no known issues.

3.0 Compatibility

NXT Readers with firmware v2.00.02 is ONLY compatible with the following:

DoorsNXT - Software v2.1.0

NXT Controllers - Firmware 2.2.14 or greater

NXT-4x4 - Firmware v02.02.03 or greater

NXT-RIM (Reader Interface Modules) - Firmware v2.02.10 or greater

Contact Keri Systems:

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: + 44 (0) 870 444 7234
Fax: (408) 435-7163	Fax: + 44 (0) 1763 274 106
Web: www.kerisys.com	Web: www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk

End of document.