

Doors.Net™ Software v3.5.1.10

Release Notes

- Section 1 - New Features
- Section 2 - Corrections and Improvements
- Section 3 - Known Issues
- Section 4 - Compatibility
- Section 5 - The Keri DVD-ROM AutoRun Program
- Section 6 - Contact Keri Systems

*NOTE: Due to networking restrictions built into the Home versions of Windows operating systems, Doors.Net software is **NOT** compatible with the Home versions of Windows XP, Windows Vista, or Windows 7.*

1.0 New Features

1. A SQL database backup feature has been implemented. A full SQL backup can be performed at any time, manually from the user interface by the System Administrator (Tools > Utilities > Backup).
2. The Live Events context menu now has a "Clear Live Events" option. This option clears events from the grid display, but does not clear events from the event database.

2.0 Corrections and Improvements

1. If a user executed the same save command, multiple times, back-to-back, command communication would fail and report a timeout. Checks have been implemented to filter out multiple instances of the same command.
2. The NXT Gateway failed with an exception if a RIM or a GIOX firmware upgrade command was performed multiple times, back-to-back. Checks have been implemented to filter out multiple instances of the same command.
3. Corrected an error when creating a Trigger in local linkage, if you select a variable to be false and select save, the "false" value would not be saved.
4. The Time Stamp when viewing controller status was not updating. The NXT Gateway has been updated to include sending the timestamp as part of the controller status report.
5. Improved NXT Gateway data throughput when handling large numbers of readers and cardholders.
6. Added checking to the System Update process to verify that if there has been no changes to a database, there is no need to update that database.
7. The software installer now checks for an open client before performing an installation. If a client is open, the installer presents a dialog box requesting the client be closed before the installation can continue.
8. The software installer also checks for any running NXT/Doors.Net services, providing the option to stop these services manually or to allow them to continue (with a forced restart following the completion of the installation).
9. Improved the process by which the software installer removes a previous installation prior to performing a new installation.
10. Corrected the Gateway Wizard tab order to correctly follow the flow of operations.
11. The software installer did not properly configure the UK English language set for operators who selected UK English.
12. Improved cardholder access rights configuration. Following a specific set of operations, cardholder access rights could be reset to default values.
13. With the Time and Attendance option enabled, the Rollcall/Tracking feature did not properly follow cardholder state through In/Out readers.
14. When in monitor mode, the Gateway would continue to send events to the Application Server when the Application Server was off line. The Gateway now recognizes if the Application Server is off line and halts monitoring mode.
15. The Application Server time stamp showing in the Auto-config status message did not match the computer's time. It was off by the difference between local time and GMT. The Server time now correctly adjusts for the GMT difference.
16. If you let the system auto generate PINs, you could not change from default value of 6 digits. The program should now allow you to set the number of digits and then auto generate PINs.
17. The optional Report Client would not install properly unless the optional Milestone client was also installed. The Report Client is no longer dependent upon the Milestone client.

Doors.Net™ Software v3.5.1.10

Release Notes

3.0 Known Issues

1. There is a communication time out issue in that a communication attempt can timeout before it is completed on a slow network such as a wireless network or VPN, or if a very large number of credentials are sent to a controller.

4.0 Compatibility

Doors.Net software v3.5.1.10 requires the following:

NXT Controllers - Firmware v02.04.17 or greater
NXT-4x4 - Firmware v02.02.05 or greater
NXT-RIM (Reader Interface Modules) - Firmware v03.01.11 or greater
GIOX (Greater I/O Board) - Firmware v01.00.10 or greater

Doors.Net software is compatible with MS readers, 26-Bit Wiegand readers, and non-26-Bit Wiegand readers in connection with the use of an NXT-RIM.

Doors.Net is NOT COMPATIBLE with PXL controllers or EntraGuard telephone entry controllers.

Due to networking restrictions built into the Home versions of Windows operating systems, *Doors.Net* software is **NOT** compatible with the Home versions of Windows XP, Windows Vista, or Windows 7.

5.0 The Keri DVD-ROM Autorun Program

The Keri DVD has an AutoRun program that opens a menu which allows you to easily locate the installation program, a training video, and technical and marketing documentation stored on the Keri DVD. Insert the DVD into your computer.

- If your host computer's AutoRun feature is enabled, the AutoRun menu appears.
- If the AutoRun feature is not enabled, use Windows Explorer™ to browse the Keri DVD. Locate and start the [autorun.exe](#) program to open the AutoRun menu.

5.1 Training Video

The *Doors.Net* DVD has a sub-folder with various AVI training videos. The AutoRun menu includes a link to the folder holding these videos. The videos are in a standard format that can be played by virtually all video players including Windows Media Player.

5.2 Product Documentation

The *Doors.Net* DVD has sub-folders with copies of technical and marketing documentation in Adobe Acrobat PDF format. The AutoRun menu includes links to the major documentation sections of the Keri DVD. All documentation is stored in Adobe's PDF format, and can be viewed using the Adobe Acrobat Reader program. The Adobe PDF format is a universal document display format that allows you to view and print copies of documents. You can install the Acrobat Reader direct from Adobe by following this link:

<http://get.adobe.com/reader/>

NOTE: The documents on the Keri DVD are the current revisions at the time of DVD release. However, these documents are subject to change at any time. If necessary, please contact Tech Support at Keri Systems or view the Technical Documentation Downloads section of the Keri web page to verify the current revision of any document.

6.0 Contact Keri Systems

| Keri USA | Keri UK, Ireland, Europe |
|--|--|
| 2305 Bering Drive San Jose, CA 95131 | Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK |
| Telephone: (800) 260-5265 (408) 435-8400 | Telephone: + 44 (0) 1763 273 243 |
| Fax: (408) 577-1792 | Fax: + 44 (0) 1763 274 106 |
| Web: www.kerisys.com | Web: www.kerisystems.co.uk |
| E-mail: sales@kerisys.com techsupport@kerisys.com | E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk |

End of document.