

NXT-4x4 Firmware v02.02.05

Release Notes

Section 1 - NXT 4x4 Firmware Release

Section 2 - Known Issues

Section 3 - Compatibility

Section 4 - Contact Keri Systems

1.0 NXT 4x4 Firmware Release

Release of the NXT 4x4 firmware v02.02.05 contains the following enhancements/fixes:

1. Reset time has been reduced from 15 seconds to 3 seconds.
2. Firmware Upgrade process has been enhanced.

2.0 Known Issues

There are no known issues for the NXT-4x4.

3.0 Compatibility

NXT-4x4 with firmware v02.02.05 is ONLY compatible with the following:

DoorsNXT - Software v2.3.0 or greater

NXT Controllers - Firmware v02.03.03 or greater

NXT-RIM (Reader Interface Modules) - Firmware v03.01.04 or greater

NXT Readers - Firmware v02.00.01 or greater

4.0 Contact Keri Systems

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: + 44 (0) 870 444 7234
Fax: (408) 435-7163	Fax: + 44 (0) 1763 274 106
Web: www.kerisys.com	Web: www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk

End of document.