

NXT Controller Firmware v2.05.60

Release Notes

1.0 NXT Controller Firmware Release

- Added new diagnostic tracking features.
- Improved controller performance should the controller be disconnected from the network.
- Updated configuration information not always being written to backup locations.
- Credential update performance improvements results in credential update times that are at least three times faster.
- Card access is not affected while credential updates are in progress (used to have to wait for sometimes lengthy updates to complete before access would be granted.)
- Error reporting for certain, rare error types could lockup a controller.
- Multiple changes made to better support GIOX hardware.

2.0 Known Issues

None at this time.

3.0 Compatibility

NXT Controllers with firmware v02.05.60 are compatible with the following:

- Doors.NET Software v3.5.1.21 or greater
- NXT Readers - 4.00.00 or greater
- NXT Readers with HID capability - 4.00.01 or greater
- Reader Interface Modules (RIMs) - 3.03.21 or greater
- 4x4 I/O Modules - 3.00.03 or greater
- GIOX Motherboard - 1.00.21 or greater
- GIOX Input Module - 1.00.10 or greater
- GIOX Output Module - 1.00.10 or greater

NXT Controllers are compatible with MS readers, 26-Bit Wiegand readers, and non-26-Bit Wiegand readers only when connected via an NXT-RIM.

4.0 Contact Keri Systems

Keri USA	Keri UK, Ireland, Europe
2305 Bering Drive San Jose, CA 95131	Unit 17 Park Farm Industrial Estate Ermine Street Buntingford Herts SG9 9AZ UK
Telephone: (800) 260-5265 (408) 435-8400	Telephone: + 44 (0) 1763 273 243
Fax: (408) 577-1792	Fax: + 44 (0) 1763 274 106
Web: www.kerisys.com	Web: www.kerisystems.co.uk
E-mail: sales@kerisys.com techsupport@kerisys.com	E-mail: sales@kerisystems.co.uk tech-support@kerisystems.co.uk

end of document